

ECE 3600 Exam 2 Information

You may write more on this sheet. You may also use Exam 1 Information

Synchronous Machines

for 60Hz systems $n_{\text{sync}} = \frac{7200\text{-rpm}}{\text{poles}}$ $\omega_{\text{sync}} = \frac{4 \cdot \pi \cdot f}{N_{\text{poles}}}$


When spinning, the induced armature voltages (E_A for our phase) depends on the field current, I_f . I_f cause the field flux (call **excitation**).

Pullout power is the maximum power a generator can produce for a given excitation, at $\delta := 90\text{-deg}$

$$P_{\text{po}} = \frac{E_A \cdot V_{\phi} \cdot \sin(90\text{-deg})}{X_s} = \frac{E_A \cdot V_{\phi}}{X_s}$$

Generators

Over-excited condition, GOOD, supplies +Q (+VARs).




Note: Voltages and currents are magnitudes, not complex numbers


The **signs** of the angles are **important!**

$$E_A \cdot \sin(\delta) = X_s \cdot I_A \cdot \cos(\theta)$$

(This θ is **negative**)





$$E_A \cdot \sin(\delta) = X_s \cdot I_A \cdot \cos(\theta)$$



$$P_{1\phi} = \frac{V_{\phi} \cdot E_A \cdot \sin(\delta)}{X_s} \quad \delta = \text{asin}\left(\frac{P_{1\phi} \cdot X_s}{V_{\phi} \cdot E_A}\right)$$

$$Q_{1\phi} = \frac{V_{\phi} \cdot E_A \cdot \cos(\delta) - V_{\phi}^2}{X_s}$$

Motors



Over-excited condition, GOOD, supplies +Q (+VARs).

(θ is measure in opposite direction to a regular load)

$$Q = V_{\phi} \cdot I_A \cdot \sin(-\theta)$$


Important relations

$$E_A \cdot \sin(|\delta|) = X_s \cdot I_A \cdot \cos(\theta)$$

$$P_{1\phi} = \frac{E_A \cdot V_{\phi} \cdot \sin(|\delta|)}{X_s}$$

$$Q_{1\phi} = \frac{V_{\phi}^2 - E_A \cdot V_{\phi} \cdot \cos(\delta)}{X_s}$$

(Bigger E_A makes Q negative (good))



Under-excited condition, BAD, absorbs +Q (+VARs).

Induction Motors

Typical torque-speed and power-speed curves for a 4-pole Induction motor

$$n_{slip} = n_{sync} - n_m = s \cdot n_{sync}$$


$$slip \ s = \frac{n_{slip}}{n_{sync}} = \frac{n_{sync} - n_m}{n_{sync}}$$

n_m = the mechanical speed of the rotor

$$= (1 - s) \cdot n_{sync}$$


$$\omega = n \cdot \left(2 \cdot \pi \cdot \frac{\text{rad}}{\text{rev}} \right) \cdot \left(\frac{\text{min}}{60 \cdot \text{sec}} \right)$$

rad/sec rpm



No slip so no induced voltage and current in the rotor and thus no torque

$$3 \cdot (I_1^2 \cdot R_1) = P_{SCL} = \text{Stator Copper Losses}$$



$$3 \cdot (I_2^2 \cdot R_2) = P_{RCL} = \text{Rotor Copper Losses}$$

$$3 \cdot \left[I_2^2 \cdot \frac{R_2}{s} \cdot (1-s) \right] = P_{conv} = (1-s) \cdot P_{AG} = \text{power converted to mechanical}$$


$$3 E_1^2 / R_C = P_{core} = \text{core loss}$$

$$P_{out} = P_{conv} - P_{mech} - P_{misc}$$

mechanical losses

$$\text{induced torque} = \tau_{ind} = \frac{P_{conv}}{\omega_m} \quad \text{OR:} \quad \tau_{ind} = \frac{P_{AG}}{\omega_{sync}} \quad (\text{N}\cdot\text{m})$$

$$\text{load torque} = \tau_{load} = \frac{P_{out}}{\omega_m}$$





Special Sensing Transformers PT or VT, Potential or Voltage Transformer, to monitor voltage.

CT, Current Transformer, to monitor current. The secondary must always be shorted or nearly shorted.

Autotransformers

Single winding, High-current (low voltage) side carries more current than any part of the winding.



Three-Phase transformers

May be 2 individual transformers wired as open Δ or T. May be 3 individual transformers. May share a single core. Lower-voltage side is often connected Δ , so that 3rd harmonic currents can flow around the Δ side without affecting external current waveforms. These connections cause a 30° phase shift. $\Delta - Y$ is usually step-up $Y - \Delta$ is usually step-down

Phase-Shifting Transformers are used to control the direction of power flow on the network.