

# ECE 3510 Exam 2 Information

This sheet and the Exam 1 Information sheet are the only reference materials allowed at exam. Bring this page.

You **may add** whatever you want to this page.

Sinusoidal responses, effects of poles & zeros, etc. Find:  $|H(j\omega)|$  and  $\angle H(j\omega)$

Steady-state AC analysis to get  $y_{ss}(t)$   $Y(\omega) = X(\omega) \cdot H(j\omega)$

Control system characteristics and the objectives of a "good" control system.

- Stable
- Tracking fast smooth minimum error (often measured in steady state)
- Reject disturbances
- Insensitive to plant variations
- Tolerant of noise

Poles on the 45° line (4% overshoot &  $\zeta = 0.707$ ). Know regions where  $\zeta >$  or  $< 0.7071$ .

Elimination of DC steady-state error, p. 61 - 63.

Rejection of constant (DC) disturbances, p. 63 - 65.

1 Closed-loop system stable

1 Closed-loop system stable

AND 2  $C(s)$  or  $P(s)$  has pole @ 0

AND 2  $C(s)$  has pole @ 0

AND 3  $C(s)$  and  $P(s)$  No zero @ 0

OR 3  $P(s)$  has zero @ 0 But bad for DC response

For all the roots of a polynomial to be in the LHP, all of the coefficients must be greater than 0. (This is sufficient for a second-order polynomial.)

## Root - Locus Plots

### a) Main rules

1. Root-locus plots are symmetric about the real axis.
2. On the real axis, spaces left of an odd number of O-L poles and zeros are always part of the locus. (Essentially, every other space on the real axis (counting leftward) is part of the plot.)
3. Each O-L pole originates ( $k = 0$ ) one branch. (n)  
Each O-L zero terminates ( $k = \infty$ ) one branch. (m)  
All remaining branches go to  $\infty$ . (n - m)

These remaining branches approach asymptotes as they go to  $\infty$ .


4. The origin of the asymptotes is the *centroid*.

$$\text{centroid} = \sigma = \frac{\sum_{\text{all}} \text{OLpoles} - \sum_{\text{all}} \text{OLzeros}}{n - m}$$


(# poles - # zeros)

5. The angles of the asymptotes

n - m	angles (degrees)		
2	90	270	
3	60	180	300
4	45	135	225



6. The angles of departure (and arrival) of the locus are almost always:



### b) Additional rules.

**Gain at any point** on the root locus:  $k = \frac{1}{|G(s)|}$

**Phase angle of G(s) at**


**any point** on the root locus:  $\arg(G(s)) = \arg(N(s)) - \arg(D(s)) = \pm 180^\circ, \pm 540^\circ, \dots$

The breakaway/in points are also solutions to:

$$\sum_{\text{all}} \frac{1}{(s + p_i)} = \sum_{\text{all}} \frac{1}{(s + z_i)}$$

**Departure angles** from complex poles:

Example.  $180 - 90 - 153.4 + 135 = 71.6^\circ$



**Mechanical translational**

**Mechanical rotational**

Through Variable (I):

F = Force (N)



T = Torque (N·m)

Across Variable (V):

v = velocity (m/sec)

ω = angular velocity (rad/sec)

Example:




**Transformers**


Equivalent impedance in primary:  $Z_{eq} = N^2 \cdot Z_2 = \left(\frac{N_1}{N_2}\right)^2 \cdot Z_2$

**Belts, chains, & gears**

r = radius of pulley or pitch radius of gears




$N = \frac{r_2}{r_1} = \frac{\omega_1}{\omega_2} = \frac{T_2}{T_1} = \text{gear tooth ratio} \left(\frac{N_2}{N_1}\right)$




**Tires, racks, & conveyors**

r = radius of wheel or pitch radius of pinion gear




$N = \frac{1}{r} = \frac{\omega}{v} = \frac{F}{T}$



Note: N = r if the input is linear motion and output is rotational.

**DC Motors**



$N = K = \frac{v_1}{\omega} = \frac{T_2}{i}$

